

General Environmental Incident Summary

Incident: 1927 **Date/Time Notice:** 5/28/2013 1320 **DEM Incident No:**
Responsible Party: American Crystal Sugar
Date Incident: 5/28/2013 **Time Incident:** 0900 **Duration:** 60 minutes
County: Pembina **Twp:** 159 **Rng:** 51 **Sec:** 14 **Qtr:** SW
Lat: 48.59303 **Long:** -97.17905 **Method:** Derived from TRS
Location Description: 8152 Old Highway 44
Drayton, ND 58225

Submitted By: Paul King **Affiliation:**
Address:
City: **State:** **Zip:**

Received By:

Contact Person: Paul King
8152 Old Highway 44
Drayton , ND 58225

Distance Nearest Occupied Building: 0 Feet

Type of Incident: Tank Overflow

Description of Released Contaminant: Pre - Molasses

Volume Spilled: 100.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

During maintenance operations conducted to drain sugar crystalizer #2 into crystalizer #4 the level sensor in #4 failed to register resulting in an overflow, a portion of which exited the area.

Risk Evaluation:

None

of Fatalities: 0

of Injuries: 0

Affected Medium: 09 - other

Potential Environmental Impacts:

None

Action Taken or Planned:

Repair or replace level sensor. Provide training to employees conducting material transfer to continuously monitor tank level physically during these operations.

Wastes Disposal Location: In the on site mud solids settling pond.

Agencies Involved:

Updates

Date: 5/28/2013 ***Status:*** Reviewed - Assigned to NDDoH Division

Author: Roberts, Kris

Updated Volume:

Notes:

This will be handled by WQ Permits Program?